



CDF Operations

- Store Summary
- Access Work
- Modifying FTMs
- Summary



Store Summary

Date	Store	Dur	Init L	Int L	Live L	Eff	Comments
4/7	2402	20.8	32.0	1406.1	1103.7	78.5%	Stack lost - test runs for last 4 hours of the store
4/9	2411	12.5	30.5	911.3	679.1	74.5%	Lost first 1h 45m of store due to L3 problems
4/11	2420	18.3	28.0	1047.2	866.8	82.8%	Lost 30 minutes when proton losses went up to 100kHz
4/12	2422	19.5	30.7	1334.7	1202.3	90.1%	Lost first 35 minutes due to L3 problems
4/13	2424	18.1	36.2	1486.7	1202.2	80.9%	COT SL8 HV trip, Silicon ISL HV trip
	Totals			6186.0	5054.1	81.7%	2h 20m average shot setup, losses below 10kHz



Access Work

Controlled Access 4/9 for Silicon

- Replaced power supply for SB1W11L3
- Buffed 2 FTMs for SB3W2/3 & IB2W0/1

Supervised Access 4/10

- Silicon completed buffing FTMs for 2 (of 8) crates
- Maintenance work on Calorimeter, Muon, & Time of Flight

Controlled Access 4/12

- Silicon buffed 3 FTMs
- Replaced 2 TDCs for COT SL7





Why Modify FTMs?

- FTMs are transition modules for Fiber Interface Boards
- 11 of 12 wire bond failures on the Silicon Detector have been due to high occupancy caused by
 - Receiving a 5th level 1 accept
 - Missing the control signal (PRD2) free a level 1 buffer
 - Missing the clock edge to latch the PRD2 signal
- Differential transmission lines for these signals are driven by chips on the FTM whose output is controlled by resistors and jumpers
- The problem has been observed and fixed in a teststand by buffing the output of the driver chips



FTM Signals





- Unbuffed and buffed control signals
- In last 8 weeks, no problems on modified FTMs
- There are 33 of 58 FTMs which still need to be modified
- Plan to take advantage of any access opportunity >1.5h
 - 1 hour of overhead and checkout
 - 15 mins to modify each board



Summary

- Recorded 5pb-1 of 6.1pb-1 delivered with 5 shifts of studies and 1 shift supervised access
- Efficiency 81.7% low due DAQ and HV problems (In part due 16 cdf scientists absent at River to River Relay Run)
- Work is proceeding to modify FTMs to improve the longterm safety of Silicon Detector